

Initial	Date
<i>[Signature]</i>	1/15/07
CMC	1/7/08

BA WTR
BA SD
Mail Stop 60189

JAN 15 2008

Memorandum

To: Project Leader, Lake Andes National Wildlife Refuge
From: Chief, Division of Water Resources
Subject: 2007-2008 Water Use Report/Management Plan

The subject reports for Lake Andes National Wildlife Refuge and Varilek, Sherman, Broken Arrow, and Roth Wildlife Production Areas have been reviewed and approved.

Attached is the completed signature page for your files. Thank you for submission of these reports.

S/ MEGAN ESTEP

Attachment

bcc: WTR rf

WTR:CCordova:cc:01/07/2008
I:\WATERUSE\SD\LAKE ANDES\wateruse_07.doc

LAKE ANDES NATIONAL WILDLIFE REFUGE COMPLEX

ANNUAL WATER USE REPORT AND MANAGEMENT PLAN

2007

Prepared by: Michael A. Benjamin Date: 12/20/07

Concurrence: Michael A. Benjamin Date: 12/20/07
Project Leader

Refuges Approval: J. Paul Con Date: 1-2-08
Refuge Supervisor

Water Resources Review: Zealand Date:

WATER USE REPORT/MANAGEMENT PLAN - SHORT FORM - REPORT YEAR: 2007

STATION NAME: Lake Andes NWR

MANAGING STATION: Lake Andes NWR Complex

WATER RIGHTS DATA

WATER RIGHT NO: 517-3 (Lake Andes)

PRIORITY DATE: 4/22/1940

SOURCE: Andes Creek, Garden Valley Creek, other tributaries

WATER DIVERTED: YES NO X (no longer) IMPOUNDMENTS: YES X NO

MEANS OF DIVERSION: n/a

AF STORAGE: 13,721 af

RATE OF DIVERSION: n/a

AF SEASONAL: 6,813 af

WELLS: YES NO X FREE FLOWING: n/a GPM or PUMPED: n/a GPM

TYPE OF USE: Fish & Wildlife: X Domestic:

Crop Irrigation: Stock:

Other:

INSPECTION DATA

Please complete all pertinent information for ACTUAL use versus the Water Rights data.

DATE OF INSPECTION: 5/8/07

INSPECTED BY: Steve Spawn, Mike Bryant

CONDITIONS AT INSPECTION: exposed shoreline on Center and South units

AF STORAGE: <20,634 af OR ESTIMATED ELEVATION: 1432.1 amsl

WELLS: FREE FLOWING: n/a GPM OR PUMPED: n/a GPM

CONDITION OF FACILITIES: Dike structures are in process of replacement during dike rehabilitation (2007/2008).

OVERALL CLIMATIC CONDITIONS: Near normal precipitation. Lake elevation is average.

PROPOSED WATER PROGRAM: No active management planned.

COMMENTS: Elevation measured for South unit. Full pool equals 1437.25'. South unit was 5.15' below full pool. North unit elevation was 1436.6, which is at full pool.

Water Resources examined the potential of the Garden Creek diversion this year. The diversion was decommissioned ~50 years ago. Hydrologist Mark Rodney determined that if the diversion were recommissioned it had the potential to contribute ~168 af of water to Lake Andes in a normal year. This equates to .04' of elevation gain over the entire lake.

WATER USE REPORT/MANAGEMENT PLAN - *SHORT FORM* - REPORT YEAR: 2007

STATION NAME: Lake Andes WMD

MANAGING STATION: Lake Andes NWR Complex

WATER RIGHTS DATA

WATER RIGHT NO: 5250-3 (Varilek WPA)

PRIORITY DATE: 12/27/1988

SOURCE: a natural slough on Varilek WPA and private land

WATER DIVERTED: YES ____ NO X

IMPOUNDMENTS: YES X NO ____

MEANS OF DIVERSION: n/a

AF STORAGE: 139 af

RATE OF DIVERSION: n/a

AF SEASONAL: n/a

WELLS: YES

NO X

FREE FLOWING: n/a

GPM or PUMPED: n/a

GPM

TYPE OF USE:

Fish & Wildlife: X

Domestic: ____

Crop Irrigation: ____

Stock: ____

Other:

INSPECTION DATA

*Please complete all pertinent information for ACTUAL use
versus the Water Rights data.*

DATE OF INSPECTION: ~7/2007

INSPECTED BY: Mike Bryant

CONDITIONS AT INSPECTION: moderate water level

AF STORAGE: <139 af

OR

ESTIMATED ELEVATION: <1614' amsl

WELLS: FREE FLOWING: n/a GPM

OR

PUMPED: n/a GPM

CONDITION OF FACILITIES: n/a

OVERALL CLIMATIC CONDITIONS: near normal precipitation

PROPOSED WATER PROGRAM: no active management

COMMENTS:

WATER USE REPORT/MANAGEMENT PLAN - *SHORT FORM* - REPORT YEAR:2007

STATION NAME: Lake Andes WMD

MANAGING STATION: Lake Andes NWR Complex

WATER RIGHTS DATA

WATER RIGHT NO: 5251-3 (Sherman WPA)

PRIORITY DATE: 12/27/1988

SOURCE: a natural slough on Sherman WPA

WATER DIVERTED: YES ☐ NO ☒

IMPOUNDMENTS: YES ☒ NO ☐

MEANS OF DIVERSION: n/a

AF STORAGE: 271 af

RATE OF DIVERSION: n/a

AF SEASONAL: n/a

WELLS: YES ☐ NO ☒

FREE FLOWING: n/a

GPM or PUMPED: n/a GPM

TYPE OF USE: Fish & Wildlife: ☒

Domestic: ☐

Crop Irrigation: ☐

Stock: ☐

Other:

INSPECTION DATA

Please complete all pertinent information for ACTUAL use
versus the Water Rights data.

DATE OF INSPECTION: ~7/2007

INSPECTED BY: Mike Bryant

CONDITIONS AT INSPECTION: moderate water level

AF STORAGE: <271 af

OR

ESTIMATED ELEVATION: <1591.7' amsl

WELLS: FREE FLOWING: n/a GPM OR

PUMPED: n/a GPM

CONDITION OF FACILITIES: n/a

OVERALL CLIMACTIC CONDITIONS: near normal precipitation

PROPOSED WATER PROGRAM: no active management

COMMENTS:

WATER USE REPORT/MANAGEMENT PLAN - *SHORT FORM* - REPORT YEAR: 2007

STATION NAME: Lake Andes WMD

MANAGING STATION: Lake Andes NWR Complex

WATER RIGHTS DATA

WATER RIGHT NO: 5077-3 (Broken Arrow WPA)

PRIORITY DATE: 10/7/1985

SOURCE: Joubert Drain

WATER DIVERTED: YES ☒ NO ☐

IMPOUNDMENTS: YES ☒ NO ☐

MEANS OF DIVERSION: Dam #7 (DU Dam)

AF STORAGE: 131.2 af

RATE OF DIVERSION: unknown

AF SEASONAL: n/a

WELLS: YES ☐ NO ☒ FREE FLOWING: n/a GPM or PUMPED: n/a GPM

TYPE OF USE: Fish & Wildlife: ☒ Domestic: ☐

Crop Irrigation: ☐ Stock: ☐

Other: recreation ☒

INSPECTION DATA

Please complete all pertinent information for ACTUAL use versus the Water Rights data.

DATE OF INSPECTION: ~7/2007

INSPECTED BY: Steve Spawn, Mark Heisinger

CONDITIONS AT INSPECTION: high water levels

AF STORAGE: <131.2 af

OR

ESTIMATED ELEVATION: unknown

WELLS: FREE FLOWING: n/a GPM

OR

PUMPED: n/a GPM

CONDITION OF FACILITIES: Water control structures in good condition.

OVERALL CLIMACTIC CONDITIONS: Near normal precipitation. The pond behind Dam #7 was full for much of the year, storing an amount of water near the limit of our water right (<131.2 af).

PROPOSED WATER PROGRAM: Management will retain as much water as possible.

COMMENTS: Joubert Drain also known as New Holland Drain.

WATER USE REPORT/MANAGEMENT PLAN - *SHORT FORM* - REPORT YEAR: 2007

STATION NAME: Lake Andes WMD

MANAGING STATION: Lake Andes NWR Complex

WATER RIGHTS DATA

WATER RIGHT NO: 6013-3 (Roth WPA)

PRIORITY DATE: 7/30/1997

SOURCE: tributary of Dry Creek

WATER DIVERTED: YES X NO

IMPOUNDMENTS: YES X NO

MEANS OF DIVERSION: ditch plug in tributary

AF STORAGE: 323 af

RATE OF DIVERSION: unknown

AF SEASONAL: 212 af

WELLS: YES NO X FREE FLOWING: n/a

GPM or PUMPED: n/a GPM

TYPE OF USE: Fish & Wildlife: X Domestic: X

Crop Irrigation: Stock:

Other:

INSPECTION DATA

*Please complete all pertinent information for **ACTUAL** use
versus the Water Rights data.*

DATE OF INSPECTION: ~7/2007

INSPECTED BY: Mark Heisinger

CONDITIONS AT INSPECTION: moderate water level

AF STORAGE: <323 af OR

ESTIMATED ELEVATION: <1398.5' amsl

WELLS: FREE FLOWING: n/a GPM OR

PUMPED: n/a GPM

CONDITION OF FACILITIES: good

OVERALL CLIMATIC CONDITIONS: near normal precipitation

PROPOSED WATER PROGRAM: no active management planned

COMMENTS:

